Oil Field Environmental Incident Summary

Responsible Party: EMERALD OIL, INC **Well Operator:** EMERALD OIL, INC **Well Name:** SHEEP FEDERAL 1A

Field Name: BOXCAR BUTTE Well File #: 12107

Date Incident:3/16/2015Time Incident:16:00Facility ID Number:County:MCKENZIETwp:148Rng:102Sec:15Qtr:

Location Description:

Submitted By: Scott Anderson Received By:

Contact Person: Scott Anderson

1600 BROADWAY, SUITE 1360

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 3 Barrels 3 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation: LEL, hazardous waste

Areal Extent:

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Pumper now understands you cannot leave pumps running unsupervised without prior approval from management to verify time away will not cause incident

Wastes Disposal Location: Indian Hills

Agencies Involved:

Updates

Date: 3/17/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.